



Flexiclean™ CWR

Overview

- Specially Designed Concentrated Alkaline Detergent
- Safely Removes Flexisperse™ CW-40 from Coated Surfaces
- Readily Dilutes in Water
- Mild to Aluminum Yet Highly Alkaline
- Easily Formulated into other User Friendly Cleaners

Applications

- Removal of Flexisperse CW-40
- Wheel Cleaner
- Floor Stripper
- All Purpose Cleaners
- Heavy Duty Cleaners

Technical Information

A powerful alkaline detergent specifically designed to ease the removal of Flexisperse CW-40 from coated surfaces. To remove Flexisperse CW-40 coatings, liberally spray an 8 % solution of Flexiclean CWR on the coating, wait 10 to 15 minutes (but do not allow the surface to dry) then pressure wash off. Repeat as needed depending on thickness of coating and substrate porosity.

In addition to removing Flexisperse CW-40, this product is an excellent building block for many other user-friendly alkaline cleaners. Although Flexiclean CWR is high in alkalinity, it is mild to aluminum. However, prolonged exposure to polished aluminum may dull the finish and as such should be tested in an inconspicuous place before use.

Typical Properties

Appearance	Clear, Colorless to Pale Yellow Liquid
Density @ 25°C	1.07 +/- 0.02 g/ml (8.9 lbs/gal)
pH (1% Sol)	9.5 +/- 1.0
Water Solubility	Soluble
Boiling Point	Approx 100°C
Odor	Mild

Packaging and Handling

Flexiclean CWR is available in 275 gallon totes (Net Wt. 2400 lbs), 55 gallon drums (Net Wt. 480 lbs) and 5 gallon pails (Net Wt. 40 lbs).

DOT Classification is Non Regulated.

This information relates only to the specific material referred to herein and not to its use in combination with any other material or in any process, unless explicitly stated herein. Such information is, to the best of our knowledge and belief, accurate and reliable as of the date compiled; however, no warranty, guarantee or other representation is made as to its accuracy, reliability, or completeness, or regarding any liabilities arising from others' intellectual property rights.